Turning the LWA unit on.

To turn unit on

Press and hold the button until all 3 lights start to flash, release the button
(unit will now configure itself).

In approximately 45 seconds the lights will start to flash.

Unit is now ready for use

Turning unit off.

To turn unit off

Press and hold the button until all 3 lights start to flash, release the button (unit will now turn OFF)

NOTE
The unit should either be on, or on charge.
Carrying a unit that has not been turned on, may make it ineffective when needed and you are unable to physical or discreetly turn it on .